ECS Configuration Change Request

CCR No. 96-0697B	**Logged Date** 10/28/96	**Rev.** B	**Request Type** CCR

Priority Routine ☐ Urgent ☒ Emergency ☐	**Affected Release** A	**Change Class** II

Title (description) Update Release A GSFC DAAC HW Diagram (Doc# 420-TD-002-003)

Documents Affected	**Source Nos** (RID, NCR, Action Item, GSFC CCR, etc.) **or Tech Reference**

RTM Change ☐   **Start New Baseline** ☐

Problem
Release A GSFC DAAC HW diagram requires update for:
1. Addition of MSS-GSFC-1.2 50 GB NFS RAID. This will be attached to CM Server MSS-GSFC-1.1

Proposed Solution
See attachment.

Impact Analysis:

Organizations Affected:

	BOO ☐	Contracts ☐	ESO ☐	FOS ☐	M&O ☐
QA ☐	Rel. A ☒	Rel. B ☐	Rel. IR1 ☐	MRS ☐	SMO ☐	Subconts ☐
A.1 ☐	Other _____				

Cost: None ☒   Small ☐ (Not exceeding $100,000)   Medium ☐ ($100,000 to $500,000)   Large ☐ (Over $500,000)

Schedule: None ☐   Other

Additional LOC _____   Man-Months _____

Materials

Originator Richard Gorsky _____

      Signature _____ Date

Office Rel A _____ Office Manager

      Signature for Manager _____ Date

Disposition	Approved ☐	Approved w/Comment ☐	Forward ☐	Disapproved ☐

Comments:

CCB Chairperson _____

      Signature   Date